MARYLAND HISTORICAL TRUST DETERMINATION OF ELIGIBILITY FORM

DETERMINATION OF ELIC	GIBILITY FORM no
roperty Name: Williams House	Inventory Number: HO-563
Address: 13110 Greenberry Lane	Historic district: yes X no
City: Clarksville Zip Code: 21029	County: Frederick
USGS Quadrangle(s): Clarksville	
Property Owner: Robert B. Williams et al.	Tax Account ID Number: 05-372216
Tax Map Parcel Number(s): 48 Tax Ma	p Number: 28
Project: MD 32 at Linden Church Road	Agency: Maryland State Highway Administration
Agency Prepared By: Maryland State Highway	
Preparer's Name: Melissa Blair	Date Prepared: 12/15/2009
Documentation is presented in: MIHP HO-563	
Preparer's Eligibility Recommendation: X Eligibility recomm	nended Eligibility not recommended
Criteria: X A B X C D Considerations: A	BCDEFG
Complete if the property is a contributing or non-contributing	resource to a NR district/property:
Name of the District/Property:	77 NO. 17
Inventory Number: Eligible:	yes Listed: yes
ite visit by MHT Staff yes X no Name:	Date:
Description of Property and Justification: (Please attach map and photo)	
In 1980, the Williams House was documented on a Maryland Historical Tr form provides a historic narrative, a detailed description of the farmhouse, significantly since 1980.	rust State Historic Sites Survey inventory form. The
The 1980 form does not describe the farm's outbuildings, which include a bank barn, and corn crib. The current owner moved the carriage house to County farm that has since been demolished. The one-and-one-half-story and features a hipped roof copula. The smokehouse is a one-story frame be standing seam metal roof. The frame equipment shed sets on a stone found stone lower level and a frame upper story sided with vertical wood siding a roof addition on the barn's east elevation. The two-story frame corn crib is crib features an opening that allows farm equipment to drive through the barn's	the Williams House property from a nearby Howard frame carriage house is clad with vertical wood siding building clad with board and batten wood siding and a dation and is sided with aluminum. The bank barn has a and covered with a metal gable roof. There is a shed is sided with a wood and sits on brick piers. The corn
The Williams House retains its historic location and the property retains the	ne integrity of its historic setting. Although the property
MARYLAND HISTORICAL TRUST REVIEW	
Eligibility recommended X Eligibility not recommended	L
Eligibility recommended	ABCDEFG
MHT Comments:	

Reviewer, Office of Preservation Services

Reviewer, National Register Program

NR Eligible: yes ×

NR-ELIGIBILITY REVIEW FORM

HO-563

Williams House


Page 2


is surrounded by neighborhoods of large single-family homes, portions of the property continue to convey a rural setting. The remaining agricultural buildings include a bank barn, corn crib, smokehouse and shed. Practicality shaped the design and layout of the farmstead with domestic and agricultural buildings clustered together to facilitate the operation of the family-run farm. The house conveys its historic design as an early nineteenth century vernacular farmhouse with Greek Revival elements. Alteration or replacement of historic building materials include the installation of aluminum siding on the house, but a large majority of historic materials are still readily visible. Historic workmanship is apparent on the interior and exterior of the house. The property retains the feeling an early-nineteenth-century farmstead and its association with Howard County's agricultural history.

The Williams House is eligible for the National Register of Historic Places (NRHP). The property is associated with events that have made a significant contribution to the broad patterns of our history, specifically the history of agriculture in Howard County (Criterion A). The property is not associated with the lives of persons significant in our past and is not eligible under Criterion B. The Williams House is eligible under Criterion C for its architecture. The property embodies the distinctive characteristics of a family farmstead of the early nineteenth through the twentieth century. The Williams House is not being evaluated under Criterion D.

The farm's period of significance dates from the early nineteenth century to 1960. The southern portion of the 155 acre property (parcel 48 on Howard County tax map 28) is not included within the historic boundary due to modern development and alterations to the viewshed. Specifically, there are two modern single-family houses on the property that have been excluded from the historic boundary. The historic boundary encompasses an area that provides a visual setting that reflects the property's significance as an agricultural property and is shown on the attached map.

MARYL	AND HISTO	DRICAL	TRUST	REVI	EW							
Eligibility	y recommen	ded		Eli	gibility not recommen	ded	_					
Criteria:	A	В	C	D	Considerations:	A	B	C	D	E	F	G
MHT Co	2003174 003144 11122-29	er, Offic	e of Pres	servatio	on Services			Date				
	Revie	wer, Na	tional Re	egister l	Program	_		Date				





HO-563 Williams House Howard County USGS Clarksville Quadrangle



0.2 Miles

0.05

Maryland State Highway Administration Cultural Resources Section Photo Log

Project No.: HO391A21

Project Name: MD 32 Linden Church

MIHP No.: HO-563

MIHP Name: Williams House

County: Howard

Photographer: Melissa Blair **Date:** December 22, 2009

Ink and Paper Combination: Epson UltraChrome pigmented ink/Epson Premium Luster Photo

Paper

CD/DVD: Verbatim, CD-R, Archival Gold

Image File Name	Description of View
HO-0563 2009-12-22 01.tif	East Elevation, view west
HO-0563 2009-12-22 02.tif	Front Entrance, view west
HO-0563 2009-12-22 03.tif	North Elevation, view south
HO-0563 2009-12-22 04.tif	North and West Elevations, view southeast
HO-0563 2009-12-22 05.tif	South Elevation, view north
HO-0563 2009-12-22 06.tif	Smokehouse, view northwest
HO-0563 2009-12-22 07.tif	Carriage House, view south
HO-0563 2009-12-22 08.tif	Shed, view northwest
HO-0563 2009-12-22 09.tif	Farmstead View, view east
HO-0563 2009-12-22 10.tif	Bank Barn South and East Elevations, view northwest
HO-0563 2009-12-22 11.tif	Bank Barn North and West Elevations, view southeast
HO-0563 2009-12-22 12.tif	Barn Door, view south
HO-0563 2009-12-22 13.tif	Bank Barn East and North Elevations, view southwest
HO-0563 2009-12-22 14.tif	Corn Crib, view southwest
HO-0563_2009-12-22_15.tif	Viewshed from House, view south
HO-0563_2009-12-22_16.tif	Viewshed from House, view north
HO-0563_2009-12-22_17.tif	Modern House on Property, view southwest



HO-563 Williams Hase Clarksville vicinity Howard Conty M. Blair Dec. 2009 MD SHPO East Elevation, view west Photo 1 of 17 HO-0563_2009-12-22_01.fif



HO-563 Williams Hase Clorksville vicinity Howard Canty M. Blowir Dec. 2009 MD SHPO Frant Entrance, view west Photo 2 of 17 HO-0563_2009-12-22_02.tif



HO-563 Williams Hase Clarks ville vicinity Howard Carry M. Blair Dec. 2009 MD STIPO North Elevation, new south Photo 3 of 17 HO-0563_2009-12-22_03. fif



HO-563 Williams Hase Clarkeville vicinity Haverd Conty M. Blair Dec. 2009 MD SHPO North and West Elevations, view southeast Photo 4cf 17 HO-0563_2009-12-22_04, Hif



HO-563 Williams Hase Clarksville vicinity Havard Conty M. Blair Dec. 2009 MD SHPO Sath Elevation, view routh Photo Sof 17 Ho-0563_2009-12-22_05.tif



HO-563 Williams House agreenille vicinity Havard County M. Blair Dec. 7009 MD SHIPO Smoke hase, view northwest Photo 6 of 17 HO-0563_2009-12-17_06.tif



410-563 Williams House Clarksville vicinty Howard Carty M. Blair Dec. 2009 MD SHPO Carriage House, view south Photo 7 & 17 HO-0563_2009-12-22_07. +if



40-563 Williams Hase Clarksville Vicinity Howard Conty M. Blair Dec. 2009 MD SHPO Shed, vica northwest Photo 8 of 17 HO-0563_2009-12-22_08.tif



HO-563 Williams Hase arterille vicinity Howard Conty M. Blair Dec. 2009 MDSHPO Formstead View view East Photo 9 of 17 HO-0563_ 2009-12-22_09-Hif



46-563 Williams Hase anterille vicinity Howard Courty M. Blair Dec. 2009 MD SHPO Bank Barn South and Gast Elevations, view northwest Photo 10 & 17 HO-0563_2009-12-22_10.HF



HO-563 Williams Hase acksille incinity Havard Carty M. Blair Dec. 2009 MD SHPO Bank Barn North and West Elevations, view sathrast Photo 11 of 17 HO-0563_2009-12-22_11:tif



HO-563 Williams Hase Clarkenille vicinity Haverd Conty M. Blair Dec. 2009 MD SHPO Barn Door, viewsath Photo 12 of 17 HO-0563_2009-12-22 11.tif



HO-563 Williams House arkaille vicinity Harard Conty M. Blair Dec. 2009 MD SHPO Bank Born East and North Elevations, Wen southwest Photo 13 of 17 40-0563_2009-12-27_13. Tit



HO-563 Williams Hase Clarksulle vicinity Howard Courty M. Blair Dec. 2009 MD SHPO Corn Crib, view sathwest Photo 14 of 17 HO-0563_ ZOO9-12-ZZ_ 14. HF



HO-563 Williams Hase Clarkeville vicinity Havard Centy M. Blair Dec. 2009 MD SHRO Viewshed from House, view sath Photo 15 of 17 HO-0563_2009-12-22_15.tif



HO-563 Williams House Clarks ville licinity Haverl Courty M. Blair Dec. 2009 MD SHPO Viewshed from Hase, view north Photo 16 of 17 HO-0563_2009-12-22_16.tif



HU-563 Williams House Clarksville vicinity Howard County M. Blair Dec 2009 MD SHPO Modern House on Property, view southwest Photo 17 of 17 HO-0563_2009-12-22_17.tif

The Williams House faces east on the east side of Linden Church Road. It is a five bay wide, one room deep, two story high, gabled roof (running north-south) frame (covered with clapboard) house, resting on a stone foundation, with a two bay wide, two bay deep, two story high, intersecting gable roof (running east-west), frame kitchen wing (a section of which is believed to have been constructed first) which creates an "L" plan.

The building features a central staircase and hall, flanked by a living room and dining room, the latter of which is connected to the original kitchen section of the house. Some alteration has been made to the upstairs building plan, to create a more workable, convenient plan, providing for two additional baths and a laundry room. Otherwise all remains intact with the first floor interior door and window frames, composed of flat pilasters and lintels with central concave flutes, joined at their corners by square blocks, matching a fine living room mantlepiece with similar stylistic detail. Wide random width floors, interior five paneled doors and original staircase are additional features of this outstanding house, constructed by Greenbury Gaither, circa 1833.

MARYLAND HISTORICAL TRUST

HO-563 District 5 Clarksville MAGI #140563 5404

INVENTORY FORM FOR STATE HISTORIC SITES SURVEY

NAME					
HISTORIC					
AND/OR COMMON The Willi	ams House				
LOCATION	J				
STREET & NUMBER	nden Church Road				
CITY, TOWN			CONGRESSIONAL DIST	RICT	
Clarksvil	.le .	VICINITY OF	6th		
Maryland			Howard		
CLASSIFIC	ATION				
CATEGORY	OWNERSHIP	STATUS	PRES	SENT USE	
DISTRICT	PUBLIC	X.OCCUPIED	X_AGRICULTURE	MUSEUM	
XBUILDING(S)	XPRIVATE	_UNOCCUPIED	COMMERCIAL	PARK	
STRUCTURE	BOTH	_WORK IN PROGRESS	_EDUCATIONAL	X-PRIVATE RESIDE	
SITE	PUBLIC ACQUISITIO	N ACCESSIBLE	ENTERTAINMENT	RELIGIOUS	
OBJECT	IN PROCESS	_XYES: RESTRICTED	GOVERNMENT	_SCIENTIFIC	
	BEING CONSIDERED	YES: UNRESTRICTED	INDUSTRIAL MILITARY	TRANSPORTATIO	
STHERTEN MILER	. Barnsley Willi	ams	Telephone #: 28	36=3234	
CITY, TOWN	nden Church Road		STATE	zip code	
Clarksvil	lle _	VICINITY OF Mar	yland 21029	zip code	
LOCATION	OF LEGAL DESC	CRIPTION	Liber #: 246		
COURTHOUSE. T	ax Map 28 blk 9,	10 10 10 10 10 10 10 10 10 10 10 10 10 1	Folio #:		
REGISTRY OF DEEDS,	ETC. Hall of Records	S	437		
STREET & NUMBER	Howard County (Court House	No.		
CITY, TOWN			STATE		
DEDDECEN	Ellicott City TATION IN EXIS	TING SUPVEVS		laryland	
-	IA HON IN EAR	III4G GORVEIS			
Howard	County Historic Sit	tes Inventory			
DATE 1978-1			XSTATE _COUNTY _LOCA	L	
DEPOSITORY FOR SURVEY RECORDS					
	Maryland Historica	II Irust	STATE		
CITY, TOWN	21 State Circle, A	Innapolis		yland	
	and outle officie, f	imaporra	7101	7	

7 DESCRIPTION

CONDITION

EXCELLENT

_GOOD

_FAIR

_DETERIORATED

_RUINS _UNEXPOSED CHECK ONE

LUNALTERED X_ALTERED

CHECK ONE

X_ORIGINAL SITE

_MOVED

DESCRIBE THE PRESENT AND ORIGINAL (IF KNOWN) PHYSICAL APPEARANCE

The Williams House faces east on the east side of Linden Church Road. It is a five bay wide, one room deep, two story high, gabled roof (running north-south) frame (covered with clapboard) house, resting on a stone foundation, with a two bay wide, two bay deep, two story high, intersecting gable roof (running east-west), frame kitchen wing (a section of which is believed to have been constructed first) which creates an "L" plan.

The woodwork and staircase in the main body of the house point to the first half of the nineteenth century. The kitchen wing is believed to be even earlier.

THE DINING ROOM

The dining room takes up the two north bays off the central hall and is lighted by two east and one north window. It features a central, paneled fireplace, with wide mitred molding on its north wall and an original wooden cupboard, east of the fireplace. A five paneled, rectangular entrance door on the east side of its south wall leads into the central hallway with a similar door centered on its west wall leading into the kitchen area. The doors and windows of this room are flanked by pilasters, holding a central concave flute, surmounted by a similar lintel joined at their corners by square blocks.

THE LIVING ROOM

The living room takes up the two south bays off the central hall, lighted by two east and west windows. Its original entrance has been widened and deepened to create closets on each side of this central opening on the south wall of the central hall. The living room is particularly lovely, featuring a central wooden mantlepiece, centered on the south wall of the living room, flanked by flat pilasters with a central concave flute, surmounted by a deep, flat, wooden lintel decorated with two similar flutes and flanked by flat pilasters, which are surmounted by square blocks. A crown molding runs around the perimeter of the ceiling of this elevation. The room also features wide, random width floors and a wide, central opening into the hall, which is centered on its south wall.

THE CENTRAL HALL

The central hall of the house runs east-west, featuring five paneled rectangular east and west entrance doors. That on the east, surmounted by a three light transom, leads out to a central three bay wide, one story high, shed roofed, open porch, supported by four square, tapered columns, resting on a flagstone landing, which runs

the width of the east elevation. That on the west may once have led to an outside porch along the south elevation of the kitchen wing.

(This section is now enclosed featuring a flag stone floor and wide south window, flanked by six-over-six light, double-hung windows, decorated with old interior shutters.) The doors are decorated with door frames, composed of pilasters, featuring a central concave flute, surmounted by a similar lintel, joined at their corners by square blocks. The staircase runs along the north wall of the hallway, featuring square balusters and original knewel post. It breaks at the landing, rather than tapering, which is found to be a feature of late eighteenth and early nineteenth century staircases. The side panels feature a curved line. This staircase leads up and around to a small landing and entrance to the south room, stopping at its east wall. Originally this second floor hall ran the depth of the house, but this shortened hall now holds a central bay, east room bath.

THE SOUTH ROOM

This south room is lighted by two east and west windows, taking up the two south bays of the main building block. It features wide, random width floors and two, wide, cross paneled, rectangular entrance doors on its north wall. That on the east side leads to a bath, that on the west side to the hall. Originally this large room was divided into two equal rooms and the bath was a part of the hall. The woodwork here is mitred, featuring flat pilasters and lintels with a central, squarely cut flute. The window frames are similar. A fireplace, centered on the south wall is covered with paneling, which

matches flanking paneled closet doors.

THE NORTH SIDE OF THE MAIN BUILDING BLOCK

The central staircase leads directly up to a wide landing over the kitchen "L" section of the house to an "L" shaped hall, off whose east wall a wide closet is placed, and further north a set of three steps, which leads to an original entrance—door into the north side of the main building block. The large north room has been divided into three areas, a small office area located in the southwest corner as you enter, a laundry area in the northwest corner and a central, open bible and cross paneled entrance, leading into another large bedroom, lighted by two east windows, which takes up two thirds of the depth of the two north bays. An original open fireplace is located on the west side of this room's north wall, flanked by flat pilasters, surmounted by a deep, projecting, flat lintel, topped by a mantle shelf. This area features new hardwood floors.

THE KITCHEN "L"

This section has undergone some alteration through the years and may originally have been a one story high, one room, frame structure, of the late eighteenth or early nineteenth century, featuring an exterior stone chimney and sleeping loft above. The main section of the house was probably constructed by Greenbury Gaither, circa 1833, when he acquired the deed to three parcels of land from Samuel I. Donaldson, trustee. The kitchen is believed to have preceded it, and

to have been added to, and its kitchen porch on the south enclosed sometime in the second half of the nineteenth century. The exterior stone chimney on the west wall of the kitchen became an interior chimney, with an enclosed staircase, leading from the first floor to the second floor and north bedroom, placed on the south side of this chimney. The upstairs north bedroom was totally separate from the rest of the house and used to house the servants. Another set of stairs (running north-south), to the second floor was used by the family, placed on the east side of the kitchen. The open porch, along the south side of the kitchen, was enclosed, a room constructed over it and a new gable roof, covering this area and the original two story high kitchen section, constructed.

Further renovations have been made by Mr. and Mrs. Barnsley Williams, descendants of Greenbury Gaither, who constructed the house. The floor of what was once an open porch has been laid in stone and a small powder room and closet added on each side of the small rectangular south window. The handhewn studs of the main building block's west wall have been exposed and filled in by brick, creating an interesting east wall for the kitchen.

8 SIGNIFICANCE

Page 1 of 3

PERIOD	AF	REAS OF SIGNIFICANCE CH	IECK AND JUSTIFY BELOW	
PREHISTORIC	ARCHEOLOGY-PREHISTORIC	COMMUNITY PLANNING	_LANDSCAPE ARCHITECTURE	RELIGION
_1400-1499	ARCHEOLOGY-HISTORIC	CONSERVATION	_LAW	SCIENCE
_1500-1599	AGRICULTURE	ECONOMICS	LITERATURE	SCULPTURE
_1600-1699	XARCHITECTURE	EDUCATION	MILITARY	_SOCIAL/HUMANITARIAN
_1700-1799	ART	ENGINEERING	MUSIC	THEATER
X 1800-1899	COMMERCE	_EXPLORATION/SETTLEMENT	PHILOSOPHY	TRANSPORTATION
_1900-	COMMUNICATIONS	_INDUSTRY	POLITICS/GOVERNMENT	XOTHER (SPECIFY)
		_INVENTION		Local history

SPECIFIC DATES

circa 1833

BUILDER/ARCHITECT

STATEMENT OF SIGNIFICANCE

The Williams House is a good example of vernacular frame architecture in Howard County, Maryland associated with the family of Greenbury Gaither, who constructed the main building block circa 1833.

Explanatory Notes

1. The main building block is solidly constructed of a hand hewn mortice and tenon, pegged building frame, the west wall of which has been further reinforced by the addition of brick fillers by Mr. and Mrs. Williams, to create a decorative kitchen wall. The interior woodwork is particularly fine, featuring five paneled, rectangular doors, wide random width floors, original staircase and mantlepieces, as well as door and window frames, composed of flat pilasters and lintels, decorated with a central concave flute, joined at their corners by square blocks.

The woodwork of the second floor is similar, but the pilasters and lintels hold a more squarely cut, central flute.

- The present owners, Mr. and Mrs. Barnsley Williams are descendents of Greenbury Gaither, who built this house for his family and operated a farm on this property. Two or three children of his children are mentioned in tran-actions found in a title search, namely; Samuel Gaither, Barbara Gaither and Mrs. Frances K. Linthicum. A Samuel G. and Laura Barnsley, a Charles and Ella Barnsley, and a George and Mary Barnsley are also mentioned giving their interest to Samuel, Elizabeth and Barbara Gaither. In the early 1900's the farm was apparently operated by Samuel Gaither and his sister, Barbara, under the management of Samuel. (78-209) Barbara's sisters, Elizabeth, Hetty, Catherine, Sarah, and Georgianna are all mentioned in the deeds of the early 1900"s found in Libers 78 and 79 in the Howard County Land Records. (Please see Title Search) In 1912, Barbara Gaither conveyed two parcels of land to George E. Talbott, her brother-in-law, for \$7,500. He and his wife, Georgia raised their only child , William E. Talbott here. In 1953 William E. Talbott, who inherited the farm, sold it to Barnsley and Frances Williams, present owners of the property.
- 3. Greenbury Gaither acquired three parcels of land by deed dated
 19 December 1833 (Anne Arundel County WSG18-471) from Samuel I.

 Donaldson, trustee. The land comprised parts of tracts of land called
 "Altogether" and "Toddy", including a parcel number 2, mentioned in
 the deed of August 1, 1953.

The main building block of the house is believed to have been constructed circa 1833 by Greenbury and Catharine Gaither and is further substantiated by Mr. Williams, whose grandmother visited her

Page 3 of 3 Significance

family here at the farm, now occupied by Mr. and Mrs. Williams. The farm was increased by some 96 acres in 1848 by the acquisition of parcel 1 from Christian Close.

HO-563 District 5 Clarksville

9 MAJOR BIBLIOGRAPHICAL REFERENCES

Land Records of Howard County Interview with Mr. and Mrs. Robert B.Williams September 23, 1980

10 GEOGRAPHICAL DATA ACREAGE OF NOMINATED PROPERTY 152.009 Acres	
Please see Attachment 1, Tax Map 28	
VERBAL BOUNDARY DESCRIPTION	
VENDAL BOOKDART DESCRIPTION	
Please see Howard County Land Records, Liber 246 Foli	0 437
LIST ALL STATES AND COUNTIES FOR PROPERTIES OVERLAPPING STATE OR COUNTY BOUNDAR	RIES
STATE Maryland COUNTY Howard	
STATE COUNTY	
11 FORM PREPARED BY	
NAME / TITLE	
Cleora Barnes Thompson, Archivist	
ORGANIZATION DATE	
Office of Planning & Zoning-Comprehensive Planning Section	
STREET & NUMBER TELEPHONE	
3450 Court House Drive	
Ellicott City STATE Maryland	
Maryland Maryland	

The Maryland Historic Sites Inventory was officially created by an Act of the Maryland Legislature, to be found in the Annotated Code of Maryland, Article 41, Section 181 KA, 1974 Supplement.

The Survey and Inventory are being prepared for information and record purposes only and do not constitute any infringement of individual property rights.

RETURN TO: Maryland Historical Trust
The Shaw House, 21 State Circle
Annapolis, Maryland 21401
(301) 267-1438



HO-563 THE WILLIAMS HOUSE Prepared by Cleora B. Thompson, AICP


DATE	LIBER-FOLIO	GRANTOR	GRANTEE	TRANSACTION	
		Barnsley, Ella B. Barnsley, John D. Barnsley & Carrie, George T. Barnsley & Mary, his wife, all of Montgomery Co.			
(d) 15 Sept. 1904	-160	Georgia Talbott & husband, George E. Talbott	Barbara Gaither	All the interest conveyed	
(e) 23 Oct. 1901	78-209	Elizabeth Gaither	Barbara Gaither	All the interest conveyed	
	"the land under the management of Samuel Gaither, her brother, containing 310 acres +				
(f) 19 March 1870	30-177	Catherine Gaither	Elizabeth, Hetty, Catherine, Sarah A., Barbara & Georgiana Gaither	Deed to parcel of land called Altogether & Toddy 96 acres + for \$4,000	
17 June 1848	8-62	Christian Close, Artemus Hearn & Elizabeth, Barbary Ann Close	Catherine Gaither	Deed to 2 parcels of land 96 acres + for \$1500	
	"together with all and singular improvements."				
Deeds Dealing with Parcel #2					
15 September 1904	79-160	Georgia Talbott & husband	Barbara Gaither	Deed to Parcel #2 for \$5.00	
18 November 1901	74-477	Catherine Gaither	George E. & Georgia Talbott	Deed to 100 acres +	
19 December 1833	AAC 18-471	"called Worthington F Samuel J. Donaldson,		Deed to 100 acres +	

Trustee


HO-563 THE WILLIAMS HOUSE Prepared by Cleora B. Thompson, AICP


Page 1 of 2


DATE	LIBER-FOLIO	GRANTOR	GRANTEE	TRANSACTION	
1 August 1953	246-437	William E. Talbott & Lenore D. Talbott	Barnsley Williams & Frances K. Williams	Deed to 2 parcels of land.	
	"all that farmowned by the descendents of Greenbury Gaither, and known as 'The Middle Farm,'comprised of 2 contiguous parcels of land containing together 206 acres 39 sq. perches ±."				
Roby West of Parcel first Described	Parcel I "in a deed dated 17 June 1848 EPH 8-62conveyed by Christian Close et al to Catherine Gaither which Catherine Gaither conveyed to Sarah Gaitner et al March 19, 1870 (30-177). P/O land called "Al- together" and "Toddy" 96 acres 39 sq. perches ±."				
Roby Farm North of second parcel	Parcel II *** "firstly described of 3 parcels of land by deed dated 19 December 1833. (AA Cty WSG 18-47 1) conveyed by Samuel I. Donaldson, Trustee, to Greenbury Gaither, which lies north of said county roadll0 acres -, heretofore described as 100 acres"				
		"George E. Talbott died 19 September 1918descended toGeorgia Talbott (widow) and William E. Talbott, his only child."			
6 January 1912	WWLC92-290	Barbara Gaither (Single)	George E. Talbott	Deed to 2 parcels of land for \$7,500.	
Deeds Dealing With Parcel #1					
(a) 23 July 1904	79-32	Samuel Gaither et al, son of Greenbury Gaither	Barbara Gaither (single)	Deed to Parcel I	
(b) 1 August 1904	79-369	Mrs. Frances K Lin- thicum, daughter of Greenbury Gaither	Barbara Gaither	All the interest conveyed for \$5.00	
(c) 15 June 1904	78-628	George C. Cashell & Kate, Samuel G. Barnsley and Laura, his wife, Charles W.	Samuel Gaither, Elizabeth Gaither, Barbara Gaither	All the interest conveyed for \$5.00	



SIMILAR BOX LOCK BATH CHINA NOBS 0 PANELING SET BR CROSS FOR PANELED CLOSET & ORIGINAL UPSTAIRS MANTLE MANTLE DOORS HALL W R W FLOOR OFFICE LAUNDRY ORIGINAL DOOR OW STEPS BATH HALL WIDE RANDOM WIDTH FLOORS CROSS PANELED DOOR\$ BR BR HARDWOOD FLOORS MITRED DEEPLY FLUTED WINDOW & DOOR FRAMES CLOSETS STAIRCASE C FIGURE 2 HO-563 The Williams House Second Floor Plan







PF



Name: The Williams House

Location: 13210 Linden Church Lane

Clarksville, Maryland

Photographer: Cleora B. Thompson, A.I.C.P.

Date of Photograph: September, 1980

Negatives in possession of the Maryland Historical Trust

View: west

Photographer looking: east Photograph number: 1 of 1

HO-563